

# Exploding Toolbox



A worker was fatally injured while grinding on the lid of a metal toolbox. The sparks from his grinder ignited an explosive mixture of oxygen and acetylene which had leaked from a torch placed inside the tool box.

The explosion caused the lid of the toolbox to fly upward, which in turn caused the grinder to hit the worker's head.

*Explosions can happen when you don't check out your environment before starting a task. Watch for hidden hazards.*