
Picture This! A Bucket Load of Problems





What's wrong with this picture? Actually, there are three things. First, the workers in the bucket are not wearing fall protection harnesses. Second, the counterweight on the lift is protruding into a traffic lane, with no traffic management practices in place, and third, there is no barricade to prevent people from walking under the boom or bucket. (Victorian WorkCover Authority, Australia)