Steel Framing Fatality File



Two Employees Injured in Fall When Steel Framing Collapses

Employees #1 and #2, both ironworkers, were standing on a framework of structural steel, unhooking a bundle of steel roof decking material. The steel framing collapsed, and they fell approximately 32 ft to the ground. Both employees sustained severe injuries, for which they were hospitalized.