## Trench Collapses and Buries New Worker



A new worker with little safety training died when the trench he was digging caved in around him. The 35-year-old plumber had been on the job for just two days. He was in a trench connecting a residential sewer line to a sewer main when the incident occurred.

The backhoe operator, working as part of the two-man crew had just finishing digging the trench and was swinging the backhoe bucket out of the seven-foot-deep hole when the victim jumped in to finish digging. Neither benched nor sloped to prevent cavein, the walls of the trench collapsed and completely buried the man.

Take responsibility for your own safety. Ask for job-specific training before performing any new or unfamiliar task. The victim in this case was provided with no safety orientation or training of any kind. The company had a written safety program, held tailgate meetings and had formal safety meetings. However they followed a 12-month cycle, which meant new employees could work a full year before receiving the job-specific training needed to perform duties safely. Newly hired employees were supposed to receive a safety orientation on the first day of employment, but the victim did not receive it before work began.

**Source:** California Fatality Assessment and Control Evaluation (FACE) Program, Case Report 05CA002